

TO BE FILLED BY THE INSPECTING OFFICER


1. Name of School : *Aroitha Vidhyalayam, Punnol*
2. Name of Officer :
3. Location : *Punnol, Thalassery South.*
4. Period for which the certificate is issued : *2021-22 Academic Year.*
5. Types of building : *3 storey RCC Building*
class room 6.36 x 6.60 x 3.60 ht.
(3 x 6 = 18 Nos.)
6. Nature of defect if any :
 - a) Foundation and basement
 - b) Super structure
 - c) Doors and windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous
7. Any major defects notice which will render the building unsafe in any manner : *NO*
8. Whether maintenance works have been done properly : *Yes.*
9. Whether the structure is sound for conducting : *Structure is sound enough to conduct classes under normal weather & wind condition.*

Note: 1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by on _____ 20_____ and found to be fit to conduct classes for the period for the reasons stated above

Place Thalassery
Date: *9/9/21*



Signature *[Handwritten Signature]*
Designation *Assistant Engineer*
Government Department
Thalassery Municipality